**WAVE DEVICES**

# WAVE DEVICES (TLK25) Release Notes

**April 2024**

# Supporting Release BASE: R01.01.01_AP_R01.02.03

4 April, 2024

Features, Enhancement & Fixes in this release:
- Fall Alert & Lone Worker
- SIM Pin Lock (applicable to TLK 25 LTE model only)
- LTE Enable/Disable (applicable to TLK 25 LTE model only)
- Power Up Experience Improvement
- Emergency Alarm Handling
- Middle Bar LED Intensity Transition Improvement
- Contact Presence Status Real Time Synchronization
- Receiving Call Audio & IPA TTS Mixed
- Wifi PWAP Improvement
- BT Pairing By End User
- Improving Voice UX for Van Gogh Portal Name/Alias creation
- Fixed incorrect location history shown on dispatch
- Fixed unable to manage contact and features in [WoC Portal]
- Fixed OnePortal failed to save new WIFI Enterprise settings
- Fixed hold PTT unable to keyup group call until rx call only recover
- Fixed unable to PTT after emergency declared and canceled
- Fixed WOC keeps on loading when trying to change device settings
- Fixed radio shown 4 bars trails after complete FOTA
- Fixed dispatcher is missing Location Reports
- Fixed TLK 25 Fails to Activate PTT Account During Deployment
- Fixed No German & Spanish language option to change on One Portal
- Fixed VA functionality stuck after successfully installed language pack
- Fixed radio does not display PWAP out of range LED after 30s not finding PWAP Wifi
- Fixed Emergency cancelation failed when the originator canceled the remote emergency
- Fixed when the user is in ambient listening state solid green top eclipse turned to purple on network change

**\*Special Notes:**
- **If the radio is unpaired to the BT accessories after FOTA, re-pair Bluetooth Accessory with either BT Open Pairing button combination or via Portal.**

# Supporting Release BASE: R01.01.01_AP_R01.01.06 (TLK25 Wi-Fi)

26 December, 2023

Enhancement & Fixes in this release
- **Precise Indoor Location (for US customer only)**
- MUC Compatibility
- Voice UI Flow & Behaviour
- Sign Off Life
- Bluetooth Pairing & Unpairing

- Power On Sequence Improvements
- Cerence Language Pack & Language Support
- WOC Portal for EMEA
- Power Up Optimization
- LED Indication for Network Down & Kodiak Down
- Optimization of Crescent LED
- QC Rebaseline
- Fixed failed to Tx audio in group call when PTT is pressed during hangtime
- Fixed Power Up fail after changing log level
- Fixed Radio shows 3-trail led & 4-trail led movement but still able to TxRx
- Fixed Radio does not unpair with BT Accy when click "Unpair" from Portal
- Fixed Device gets stuck when back to back emergency calls declared and canceled
- Fixed Radio should not proceed with the FOTA upgrade if the battery is very low
- Fixed Radio does not play accy connected tone during Power Up Sequence when attaching wired accy before radio power up (differ when attaching USB/MUC charger)
- Fixed Device does not connect to KODIAK after entering WifiAP through Maintenance Mode
- Fixed unable to connect to kodiak after radio wipe
- Fixed Radio unable to connect to WiFi after configure using Maintenance Mode [Intermittent]
- Fixed missing Radio Information in Maintenance Mode
- Fixed missing voice prompt "Logs Uploading" during power up sequence
- Fixed Missing VA when trigger diagnostic log after perform radio wipe (Intermittent)
- Fixed connectivity process glitched by USB charging LED
- Fixed after turning off Floor Error/Busy Tone, it does not reflected as OFF on Portal
- Fixed Wave PTT App Memory Leak
- Fixed unable to register new device & add user on WOC Portal
- Fixed unable to access to Device Management for One Portal (Operator)
- Fixed resync icon is not getting enabled even after selecting the contacts from the corp management PTT user list.
- Fixed Radio keeps showing 4 trail bar LED, unable to login Kodiak
- Fixed register device using Cloning - Unable to clone WiFi & BT values to destination device [WOC Portal]
- Fixed after Battery drain, device is not activated after plugged into charging
- Fixed Device unable to Tx call after left idle for 30 minutes
- Fixed unable to Resync on One Portal (Staging)
- Fixed after receiving an emergency cancel from a user during an emergency call, the orange crescent is still shown while the now normal call continues.
- Fixed VanGogh Device Deletion From OnePortal Does Not Get Reflected In CAT
- Fixed PTT press after private call ended will initiate another new private call instead of group call
- Fixed receive Declare Fail during network down
- Fixed Private Call Missing Missed Alert Tone
- Fixed after Mute is disabled, the device still displays Mute on/off

**\*Special Notes:**
- **If the device is not obtained directly from the factory, perform a Radio Wipe prior to registering the device into WAVE PTX Portal.**
- **If you fail to Activate PTT Account During Deployment, either press PTT once to retry, or power cycle the device.**
- **If the radio is not connected to BT accessories after FOTA, please power cycle the device.**

## Supporting Release BASE: R01.00.01_AP_R01.00.05 (TLK25 Wi-Fi)

31 July, 2023

Features in This Release
- Power
- Device Status & Menu Structure
- Battery
- Volume (+/-)
- Mute/Unmute
- PTT Lock
- Push Notification
- Voice Assistance Interactions
- Private Call PTT
- Group Call PTT
- Ambient Listening
- Broadcast Call
- Radio Scan
- Wifi
- Do Not Disturb (DND)
- Query Time
- Supervisor Override
- Signal Out of Range
- IPA
- Emergency Alert
- FOTA Status
- Diagnostic Trigger
- Diagnostic Log
- RX Radio Stun
- RX User Disable
- Factory Reset Mode
- Maintenance Mode
- Manual Test Mode
- Service Code / Error Code
- Wifi Enterprise
- GNSS (Location Service / Indoor Location)
- Contact List
- Mode Change