



APX Portable Firmware Update for PMNN4547 Battery

MOTOROLA, MOTO, MOTOROLA SOLUTIONS and the Stylized M logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license.

All other trademarks are the property of their respective owners.

© 2017 Motorola Solutions, Inc. All rights reserved.



MN004560A01-AA

Important: APX6000/APX6000XE/APX7000/APX7000XE/SRX2200 users should schedule firmware update prior to using the new UL PMNN4547 battery as older firmware versions do not recognize the new UL battery. Failure to upgrade radios to R16.30.00 leads to persistent low battery alert regardless of battery capacity.

Required Software: APX Firmware Release R16.30.00 or later; hardware upgrade is not required.

Refer to bulletin MTN-0001-17-NA for additional details or contact your Motorola Solutions technical support center at https://www.motorolasolutions.com/en_us/support.html.