

APX Portable Firmware Update for PMNN4573 and PMNN4547 Batteries

MOTOROLA, MOTO, MOTOROLA SOLUTIONS and the Stylized M logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC and are used under license.

All other trademarks are the property of their respective owners.

© 2018 and 2023 Motorola Solutions, Inc. All rights reserved.

Printed in



MN005442A01-AB

Important: APX 6000/APX 6000XE/APX 7000/APX 7000XE/
APX 8000H/APX 8000HXE/SRX 2200 radio users
should schedule firmware update prior to using the new
UL PMNN4573 and PMNN4547 batteries as older
firmware versions do not recognize the new UL
batteries. Failure to upgrade radios to R25.01.00 leads
to persistent low battery alert regardless of battery
capacity.

Required Software: APX Firmware Release R25.01.00 or later;
hardware upgrade is not required.

For additional details, kindly contact your Motorola Solutions
technical support center at
https://www.motorolasolutions.com/en_us/support.html.