

PMNN4491D_ Battery Quick Reference Guide



MN009584A01-AB

IMPORTANT NOTICE

APX900, APX1000i, and VX-P949 USERS:

To ensure proper operation when using PMNN4491D_ battery, update APX900/APX1000i/VX-P949 radio firmware to R28.30.00 or greater.



Printed in



PMNN4491D_ IMPRES battery is now equipped with the self-calibration feature that can be identified by the self-calibration logo on the battery label. Batteries with self-calibration feature do not require the IMPRES calibration process, when charged with the following chargers.

Figure 1 : IMPRES Single-Unit Charger (New Generation)




Table 1: SUC Part Number

Part Number	Description
PMPN4576_	United States and Canada Plug
PMPN4573_	Argentina Plug
PMPN4575_	Brazil Plug
PMPN4572_	United Kingdom Plug
PMPN4577_	Europe Plug
PMPN4571_	Australia and New Zealand Plug
PMPN4578_	Japan Plug
PMPN4574_	Korea Plug
PMPN4579_	China Plug
PMPN4582_	India Plug

Figure 2 : IMPRES Multi-Unit Charger (Software Version V2.05* and Later)




Table 2: MUC Part Number

Part Number	Description
PMPN4284_	United States and Canada Plug
PMPN4290_	United Kingdom Plug
PMPN4289_	Europe Plug
PMPN4293_	Australia and New Zealand Plug
PMPN4291_	Argentina Plug

Table 2: MUC Part Number

Part Number	Description
PMPN4292_	Brazil Plug
PMPN4295_	Japan Plug
PMPN4294_	Korea Plug
PMPN4296_	China Plug
PMPN4462_	Taiwan Plug

* You can update the IMPRES 2 MUC to the latest software version using the MSI Charger Reprogrammer

Installation Software. (https://www.motorolasolutions.com/en_xu/products/two-way-radio-accessories/charger-accessories/charger-accessories/nntn7676.html).

You can obtain the installation guide in the software download package.

Note: If the PMNN4491D_ IMPRES battery is initially inserted into an IMPRES charger with an older software, the charger begins the initialization process with a solid yellow indication. Do not remove the battery from the charger until the charger indicates solid green. This process can take up to 8 hours.

MOTOROLA, MOTO, MOTOROLA SOLUTIONS, and the Stylized M logo are trademarks or registered trademarks of Motorola Trademark Holdings, LLC, and are used under license. All other trademarks are the property of their respective owners.

© 2022 Motorola Solutions, Inc. All rights reserved.

NOTES